

# WEHIRE SURFACE PREPARATION EQUIPMENT

## CONNECTING 3 PHASE FLOOR SAW TO MAINS SUPPLY FROM WALL SOCKETS IN FACTORY

WALL SOCKET  
3 PHASE MAINS  
SUPPLY  
NEEDS TO BE  
5 PIN 32AMP  
OUTLET



32AMP 3PHASE  
5PIN LEAD  
15MTRS LONG



3 PHASE 415V 32AMP 5 PIN  
EXTENSION LEADS,



OR WE CAN SUPPLY  
63AMP TAIL TO REDUCE  
TO 32AMP 5 PIN IF  
MAINS SOCKET IS  
63AMP 5PIN



TAIL ADAPTOR MAY BE USED  
TO CONNECT TO 16AMP  
SOCKET AND GIVE 32AMP  
CONNECTION OR MAY BE  
DIRECT CONNECTION.



PHASE INVERTER PLUG FITTED  
TO FLOOR SAW NEEDS TO BE CHANGED  
TO ENSURE CORRECT ROTATION AND  
DIRECTION FOR SAW TO CUT.

