

# WEHIRE SURFACE PREPARATION EQUIPMENT

## CONNECTING 3 PHASE FLOOR SAW TO MAINS SUPPLY FROM WALL SOCKETS IN WALL

WALL SOCKET  
3 PHASE MAINS  
SUPPLY  
NEEDS TO BE  
5 PIN 32AMP  
OUTLET



32AMP 3PHASE  
5PIN LEAD  
15MTRS LONG



32AMP 3PHASE  
5PIN LEAD  
15MTRS LONG



PHASE INVERTER PLUG FITTED TO FLOOR SAW  
NEEDS TO BE CHANGED TO ENSURE CORRECT  
ROTATION AND DIRECTION FOR SAW TO CUT.

USE FLAT BLADE SCREWDRIVER AND PUSH INTO  
SLOT THEN TURN TO SWITCH PINS.

