

W_EH_IRE **SURFACE PREPARATION** **EQUIPMENT**

WALL SOCKET
 3 PHASE MAINS
 SUPPLY
 NEEDS TO BE
 5 PIN 32AMP
 OUTLET



32AMP 3PHASE
 5PIN LEAD
 15MTRS LONG




3 PHASE 415V 32AMP 5 PIN
 EXTENSION LEADS,



CONNECTING 3 PHASE DFG 250 SINGLE HEAD TO MAINS
 SUPPLY FROM WALL SOCKETS IN FACTORY

240V MAINS SUPPLY



5KVA TRANSFORMER



SPE 316 DUST
 CONTROL UNIT



32AMP 110V LEADS 110V
 EACH ONE IS 14M LONG



5 MTR HOSE FOR
 DUST



PHASE INVERTER PLUG FITTED
 TO GRINDER NEEDS TO BE CHANGED
 TO ENSURE CORRECT ROTATION AND
 DIRECTION FOR WHEN USING PCD COMBI

