

WEHIRE SURFACE PREPARATION EQUIPMENT

WALL SOCKET
3 PHASE MAINS
SUPPLY
NEEDS TO BE
5 PIN 32AMP
OUTLET



32AMP 3PHASE
5PIN LEAD
15MTRS LONG



3 PHASE 415V 32AMP 5 PIN
EXTENSION LEADS,



TAIL ADAPTOR MAY BE USED
TO CONNECT TO 16AMP
SOCKET AND GIVE 32AMP
CONNECTION OR MAY BE
DIRECT CONNECTION.



PHASE INVERTER PLUG FITTED
TO FLOOR SAW NEEDS TO BE CHANGED
TO ENSURE CORRECT ROTATION AND
DIRECTION FOR SAW TO CUT.



CONNECTING 450mm 3 PHASE FLOOR SAW TO
MAINS SUPPLY FROM WALL SOCKETS IN
FACTORY

Cuts up to 165mm deep
Must have constant water supply