

WEHIRE SURFACE PREPARATION EQUIPMENT

CONNECTING 3 PHASE BARON MIXER TO MAINS SUPPLY FROM WALL SOCKETS IN FACTORY

WALL SOCKET
3 PHASE MAINS
SUPPLY
NEEDS TO BE
5 PIN 32AMP
OUTLET



32AMP 3PHASE
5PIN LEAD
15MTRS LONG



3 PHASE 415V 32AMP 5 PIN
EXTENSION LEADS,



OR WE CAN SUPPLY
63AMP TAIL TO REDUCE
TO 32AMP 5 PIN IF
MAINS SOCKET IS
63AMP 5PIN



TAIL ADAPTOR MAY BE USED
TO CONNECT TO 16AMP
SOCKET AND GIVE 32AMP
CONNECTION OR MAY BE
DIRECT CONNECTION.



PHASE INVERTER PLUG FITTED
TO MIXER NEEDS TO BE CHANGED
TO ENSURE CORRECT ROTATION AND
DIRECTION FOR MIXING

