

WEHIRE SURFACE PREPARATION EQUIPMENT

WALL SOCKET
3 PHASE MAINS
SUPPLY
NEEDS TO BE
5 PIN 32AMP
OUTLET



32AMP 3PHASE
5PIN LEAD
15MTRS LONG




3 PHASE 415V 32AMP 5 PIN
EXTENSION LEADS,



CONNECTING 3 PHASE BEF 275 SCABBLER TO MAINS SUPPLY FROM WALL SOCKETS IN FACTORY

240V MAINS SUPPLY



5KVA TRANSFORMER



SPE 316 DUST
CONTROL UNIT



32AMP 110V LEADS 110V
EACH ONE IS 14M LONG



PHASE INVERTER PLUG FITTED
TO SCABBLER NEEDS TO BE CHANGED
TO ENSURE CORRECT ROTATION AND
DIRECTION FOR CUTTING HEAD
TO THE ARROW ON MACHINE



5 MTR HOSE FOR
DUST

