

WALL SOCKET  
3 PHASE MAINS  
SUPPLY  
NEEDS TO BE  
5 PIN 32AMP  
OUTLET



TAIL ADAPTOR MAY BE USED  
TO CONNECT TO 63AMP  
SOCKET AND GIVE 32AMP  
CONNECTION OR MAY BE  
DIRECT CONNECTION



**WE HIRE**  
**SURFACE PREPARATION**  
**EQUIPMENT**  
TEL 01633 619129

**CONNECTING 3 PHASE DFG700 GRINDER TO MAINS  
SUPPLY FROM WALL SOCKETS IN FACTORY**



PHASE INVERTER PLUG FITTED  
TO DFG700 GRINDER TO TURN PHASE  
ROTATION WHEN USING  
DIRECTIONAL DIAMONDS SUCH AS PCD



SWING WEIGHTS CAN BE USED IN REAR POSITION TO MAKE HEAD LIGHTER BETTER WHEN USED WITH PCD COMBI PLATES  
OR IF SURFACE IS SOFT.

CAN BE USED IN FRONT POSITION TO MAKE HEAD HEAVIER AND USED WHEN GRINDING HARDER SURFACES.