

WEHIRE SURFACE PREPARATION EQUIPMENT

CONNECTING A GENERATOR TO RUN A 110V FLOOR MACHINE AND DUST CONTROL UNIT

50 KVA 3 PHASE GENERATOR



63AMP TO 5PIN
32AMP TAIL 3PHASE



10KVA 3PHASE SITE
TRANSFORMER FITTED WITH
32AMP 3 PHASE 5 PIN PLUG



32AMP 3PHASE
5PIN LEAD
15MTRS LONG



CONNECT NO MORE THAN TWO
32AMP 4MM 110V LEADS INTO ONE
OF THE 32A SOCKETS



CONNECT NO MORE THAN TWO
32AMP 4MM 110V LEADS INTO ONE
OF THE 32A SOCKETS



CONNECT YOUR APPLIANCE TO NO MORE THAN
TWO EXTENSION LEADS



REMOVE HOSE FROM DRUM , CONNECT UP TO APPLIANCE



or or

